



MEDIA INFORMATION / PUBLIC INFORMATION WORKSHEET

Please email to PIO Larry Gallegos at lagallegos@bernco.gov (505) 228-6668

1. Date/Incident number	03/30/2017 2017-004898
2. Incident Address	Giraud and Tapia
3. Area of County	South Valley
4. Mutual Aid request/given	None
5. Reported by:	Resident
6. Fire Condition/Alarms (working fire, 2 nd alarm)	Small working residential fire
7. Size & Type of Structure/Incident (apt/residential home/ bldg)	Single story residence (2 nd house on property) with a fire in the laundry room.
8. Number of Personnel Responded (Units and FFs)	E32, R32, E33, R33, TR38, R34, BAT8, BAT6, FMO6 = 20 personnel
9. Time Dispatched/1 st Unit Arrival time	Dispatched – 13:36 1 st unit arrived – 13:45
10. Brief description of what 1 st unit on the scene saw.	An approx. 1000 sq ft single sotry house with smoke coming from the front door. Residents evacuation and crews encountered fire in the laundry room area
11. Total time to bring fire under control	20 mins
12. Anyone inside at the time of the fire. If yes, how many	Yes – a mom and her young son
13. How was family alerted? (smoke detector, neighbors)	Smell of smoke
14. Injuries? If yes, include age, gender, transport info & injuries sustained.	No injuries reported
15. Fire Origin? Was it contained to origin?	Dryer in the laundry room
16. Spread through %	Approx. 10-15% of the house
17. Smoke Damage (light or heavy smoke damage throughout)	Approx. 50%
18. Cause (determinded/undetermined -->accident,natural,incendiary)	Fire appeared to originate from the dyer vent in the laundry room
19. Estimated Damages (structural, contents/vehicle)	Approx. 20-30,000 structural and contents
20. Assisting Agencies like Red Cross, # of displaced?	Referred to Red Cross for resident assistance
21. Contributing factors such as wind or location	None
22. Additional information (rescues, FF injuries and so on)	No FF injuries noted
23. On Scene POC	
24. Community Risk Reduction Message	Dryer vents can overheat and begin combustion. Frequently clean dryer vents and maintain clear ventilation for heat produced by dryers.
25. Additional Information	