



MEDIA INFORMATION / PUBLIC INFORMATION WORKSHEET

Please email to PIO Larry Gallegos at lagallegos@bernco.gov (505) 228-6668

1. Date/Incident number	11/24/15, Incident #2015-017096
2. Incident Address	710 Tyler NE
3. Area of County	Dist. 36
4. Mutual Aid request/given	No
5. Reported by:	Resident
6. Fire Condition/Alarms (working fire, 2 nd alarm)	Chimney fire
7. Size & Type of Structure/Incident (apt/residential home/ bldg)	Approximately 2000 sq. ft., single family, residential
8. Number of Personnel Responded (Units and FFs)	8 units/17 personnel responded to scene: BAT6, TWR36, R36, E30, R30, E31, R31, FMO 30. PNM, NM Gas & AAS also were on scene.
9. Time Dispatched/1 st Unit Arrival time	Time dispatched, 23:24, 1 st unit on scene , 23:28
10. Brief description of what 1 st unit on the scene saw.	Dispatch had advised probable false alarm, all units remained en-route until it could be confirmed. On arrival smoke was curling up around the chimney and eaves near the alpha/delta corner, and embers dropping near S.O. standing on scene. At this time it was declared a working fire.
11. Total time to bring fire under control	55 minutes
12. Anyone inside at the time of the fire. If yes, how many	1
13. How was family alerted? (smoke detector, neighbors)	CP advised smoke in living room not coming from fireplace.
14. Injuries? If yes, include age, gender, transport info & injuries sustained.	No
15. Fire Origin? Was it contained to origin?	Roof & eaves near fireplace. Fire Contained to roof and attic area.
16. Spread through %	1%
17. Smoke Damage (light or heavy smoke damage throughout)	Light
18. Cause (determined/undetermined -->accident,natural,incendiary)	Accidental, possibly through faulty firebrick in chimney.
19. Estimated Damages (structural, contents/vehicle)	\$5000
20. Assisting Agencies like Red Cross, # of displaced?	None
21. Contributing factors such as wind or location	None
22. Additional information (rescues, FF injuries and so on)	None
23. On Scene POC	N/A
24. Community Risk Reduction Message	Proper chimney cleaning and inspection may have alerted the occupants to faulty chimney construction or needed repairs.
25. Additional Information	

