



MEDIA INFORMATION / PUBLIC INFORMATION WORKSHEET

Please email to PIO Larry Gallegos at lagallegos@bernco.gov (505) 228-6668

1. Date/Incident number	4/27/17 2017-006486
2. Incident Address	Lake @ Goff SW
3. Area of County	South Valley
4. Mutual Aid request/given	Yes. Heavy Technical Rescue strike team,
5. Reported by:	Neighbor
6. Fire Condition/Alarms (working fire, 2 nd alarm)	Heavy fire conditions with roof collapsing upon arrival.
7. Size & Type of Structure/Incident (apt/residential home/ bldg)	Two Story residential structure approx. 1400 square feet.
8. Number of Personnel Responded (Units and FFs)	41 personnel. Bat-6, Bat-8, Chf-3, E-32, E-33, E-34, Tr-38, AFD E-7, S-3,E-3, R-3, Bat-4, HTRTF-1, R-32, R-33, R-34, R-38, Rehab-1, FMO-6, FMO-7
9. Time Dispatched/1 st Unit Arrival time	14:54 Dispatched 14:58 Arrived
10. Brief description of what 1 st unit on the scene saw.	Units arrived to a two story residential structure with heavy fire conditions and roof collapsing.
11. Total time to bring fire under control	Under control @ 16:16 1 hour and 18 minutes
12. Anyone inside at the time of the fire. If yes, how many	Initial reports were advising of one possibly several persons trapped inside of structure.
13. How was family alerted? (smoke detector, neighbors)	Vacant structure
14. Injuries? If yes, include age, gender, transport info & injuries sustained.	None
15. Fire Origin? Was it contained to origin?	Undetermined
16. Spread through %	100%
17. Smoke Damage (light or heavy smoke damage throughout)	Total loss
18. Cause (determined/undetermined -->accident,natural,incendiary)	Undetermined
19. Estimated Damages (structural, contents/vehicle)	\$60,000
20. Assisting Agencies like Red Cross, # of displaced?	AFD heavy rescue collapse strike team and Public Works for excavating equipment
21. Contributing factors such as wind or location	High wind created a wind driven fire increasing fire behavior.
22. Additional information (rescues, FF injuries and so on)	No victims found after digging out structure
23. On Scene POC	
24. Community Risk Reduction Message	Ensure vacant structures are secured appropriately.
25. Additional Information	Due to instability of structure after collapse of roof and flooring, heavy equipment was needed to stabilize the structure and remove debris for victim search.