



## MEDIA INFORMATION / PUBLIC INFORMATION WORKSHEET

Please email to PIO Larry Gallegos at [lagallegos@bernco.gov](mailto:lagallegos@bernco.gov) (505) 228-6668

1. Date/Incident number	11/15/2015 - 2015-016637
2. Incident Address	1 Lost Horizon Blvd
3. Area of County	West Mesa Area North of I-40
4. Mutual Aid request/given	None
5. Reported by:	Facility Worker
6. Fire Condition/Alarms (working fire, 2 <sup>nd</sup> alarm)	Working fire – 1 <sup>st</sup> alarm only with additional tenders (TN-33 and TN-31 TN-31 was canceled prior to arrival
7. Size & Type of Structure/Incident (apt/residential home/ bldg)	Approx 3000 sq ft cinder block facility that housed an office in a quarter of the building and a workshop in the rest
8. Number of Personnel Responded (Units and FFs)	Bat-8 – 1 commander Bat-6 – 1 commander E-32 – 3 personnel E-33 – 3 personnel TR-38 – 3 personnel R-32 – 2 personnel R-33 – 2 personnel R-34 – 2 personnel TN-33 – 2 personnel (from R-38) TN-31 – 2 personnel (from R-31) FMO 30-1 personnel
9. Time Dispatched/1 <sup>st</sup> Unit Arrival time	Dispatch – 05:25 1 <sup>st</sup> unit arrived – 05:46
10. Brief description of what 1 <sup>st</sup> unit on the scene saw.	Heavy smoke and flames coming from the office area of the building with moderate winds pushing the smoke to the north. Green flames were noted indicating flammable gas in the building (it was reported that there were oxygen and acetylene tanks for welding in the building)
11. Total time to bring fire under control	37 minutes from arrival of the first unit
12. Anyone inside at the time of the fire. If yes, how many	No
13. How was family alerted? (smoke detector, neighbors)	Facility workers arrived to find the building filled with smoke
14. Injuries? If yes, include age, gender, transport info & injuries sustained.	None
15. Fire Origin? Was it contained to origin?	FMO-30 determined the fire was started by a heater that was attached to the outside of the building
16. Spread through %	20-30% of the building
17. Smoke Damage (light or heavy smoke damage throughout)	Heavy smoke damage in the area of origin and light smoke damage throughout the building
18. Cause (determined/undetermined -->accident,natural,incendiary)	Accidental – (Per FMO-30) External heater attached to the building
19. Estimated Damages (structural, contents/vehicle)	Approx. 40000
20. Assisting Agencies like Red Cross, # of displaced?	None
21. Contributing factors such as wind or location	Moderate wind at approx. 10-15 mph and distance to the scene – 23 min response time due to distance
22. Additional information	No FF injuries

(rescues, FF injuries and so on)	
23. On Scene POC	Elisa Armijo – Facility manager – 505- 977-7569
24. Community Risk Reduction Message	Check heaters and clean filters
25. Additional Information	Location was the FAA West Mesa Long Range Radar that monitors a 200 mile radius. The radar was not affected and crews did a great job containing the fire to the building and room of origin.