



MEDIA INFORMATION / PUBLIC INFORMATION WORKSHEET

Please email to PIO Larry Gallegos at lagallegos@bernco.gov (505) 228-6668

1. Date/Incident number	12/27/15, 15F-018782
2. Incident Address	2612 Ocatillo
3. Area of County	Bernalillo County South Valley
4. Mutual Aid request/given	N/A
5. Reported by:	Call to 911
6. Fire Condition/Alarms (working fire, 2 nd alarm)	1 alarm mobile home fire
7. Size & Type of Structure/Incident (apt/residential home/ bldg)	1500 sq. ft. mobile home
8. Number of Personnel Responded (Units and FFs)	18 personnel, and 9 units responded
9. Time Dispatched/1 st Unit Arrival time	Dispatched at 02:42, with first unit arriving at 02:52
10. Brief description of what 1 st unit on the scene saw.	First on scene unit found a double wide mobile home with smoke, and flames coming from the roof on the back side of the residence.
11. Total time to bring fire under control	Fire under control in 29 minutes.
12. Anyone inside at the time of the fire. If yes, how many	Residence was unoccupied at time of fire.
13. How was family alerted? (smoke detector, neighbors)	Smoke detectors were alarming upon fire crews making entry
14. Injuries? If yes, include age, gender, transport info & injuries sustained.	none
15. Fire Origin? Was it contained to origin?	Fire contained to the kitchen area, and some extension into the roof
16. Spread through %	25% of the home was involved.
17. Smoke Damage (light or heavy smoke damage throughout)	Heavy in the kitchen area and light smoke damage in the rest of the structure.
18. Cause (determined/undetermined -->accident,natural,incendiary)	Under investigation
19. Estimated Damages (structural, contents/vehicle)	Estimated \$30,000.00 in damages
20. Assisting Agencies like Red Cross, # of displaced?	none
21. Contributing factors such as wind or location	Freezing weather conditions, with blowing snow.
22. Additional information (rescues, FF injuries and so on)	none
23. On Scene POC	N/A
24. Community Risk Reduction Message	Had the residence been occupied they would have been alerted by the installed battery operated smoke detectors.
25. Additional Information	N/A