



MEDIA INFORMATION / PUBLIC INFORMATION WORKSHEET

Please email to PIO Larry Gallegos at lagallegos@bernco.gov (505) 228-6668

1. Date/Incident number	11/24/2015 Incident number – 2015-017099
2. Incident Address	2324 Metzger Rd SW
3. Area of County	South Valley
4. Mutual Aid request/given	None
5. Reported by:	Unknown neighbor
6. Fire Condition/Alarms (working fire, 2 nd alarm)	Fully engulfed working fire, no 2 nd alarm needed or requested
7. Size & Type of Structure/Incident (apt/residential home/ bldg)	12x50 mobile home
8. Number of Personnel Responded (Units and FFs)	E-34, E-33, TR-38, R-34, R-33, R-38, BAT-8, FMO-30, FMO Chief (3) (3) (3) (2) (2) (2) (1) (1) (1) = 18 total
9. Time Dispatched/1 st Unit Arrival time	Dispatched – 00:59 Arrived – 01:02
10. Brief description of what 1 st unit on the scene saw.	E-34 reported they could see flames from the station when they went enroute and upon their arrival they found a fully engulfed mobile home with arching powerlines and fire coming from the gas meter as well.
11. Total time to bring fire under control	27 Miutes
12. Anyone inside at the time of the fire. If yes, how many	Initial report from the property owner that lived next door, was there was a possibility of someone (who was staying there illegally and accessing the residence from underneath the building) inside but no one was found after multiple searches inside and under the mobile home.
13. How was family alerted? (smoke detector, neighbors)	Neighbor called 911 after they saw flames from the building
14. Injuries? If yes, include age, gender, transport info & injuries sustained.	None
15. Fire Origin? Was it contained to origin?	Fire did damage powerline going to the property (which was arching upon arrival of crews) but otherwise contained to the building.
16. Spread through %	100% - total loss
17. Smoke Damage (light or heavy smoke damage throughout)	Heavy flame damage – total loss
18. Cause (determind/undetermined -->accident,natural,incendiary)	Cause under investigation/Undetermined
19. Estimated Damages (structural, contents/vehicle)	Approx - \$50,000 for building and contents
20. Assisting Agencies like Red Cross, # of displaced?	None
21. Contributing factors such as wind or location	None
22. Additional information (rescues, FF injuries and so on)	No FF injuries were reported.
23. On Scene POC	Peggy Dillingham – property owner
24. Community Risk Reduction Message	Building did not have any detection systems in place
25. Additional Information	Thanksgiving Safety information for Turkey Frying. Do not place frozen turkey in hot grease. Will likely cause significant thermal burns.