



MEDIA INFORMATION / PUBLIC INFORMATION WORKSHEET

Please email to PIO Larry Gallegos at lagallegos@bernco.gov (505) 228-6668

1. Date/Incident number	11/6/2015 2015-016125
2. Incident Address	1504 Lucyle PL NW
3. Area of County	North Valley
4. Mutual Aid request/given	Mutual Aid requested from Albuquerque Fire Dept.
5. Reported by:	Alarm Company- Alarm System, Smoke Alarm
6. Fire Condition/Alarms (working fire, 2 nd alarm)	Smoke on second floor, fire in HVAC unit on the roof.
7. Size & Type of Structure/Incident (apt/residential home/ bldg)	Approximately 3000 square ft., 2 story residential home.
8. Number of Personnel Responded (Units and FFs)	13 Units, 27 Firefighters
9. Time Dispatched/1 st Unit Arrival time	Initial dispatch single Engine at 8:37 PM, arrived at 8:47 PM.
10. Brief description of what 1 st unit on the scene saw.	Smoke and flames coming from roof
11. Total time to bring fire under control	Approximately 30 minutes
12. Anyone inside at the time of the fire. If yes, how many	None
13. How was family alerted? (smoke detector, neighbors)	No occupants were home at time of alarm, alarm company notified Fire Department.
14. Injuries? If yes, include age, gender, transport info & injuries sustained.	None
15. Fire Origin? Was it contained to origin?	Origin on roof in HVAC unit, contained to area of origin.
16. Spread through %	5%
17. Smoke Damage (light or heavy smoke damage throughout)	Moderate smoke damage on second floor.
18. Cause (determined/undetermined -->accident,natural,incendiary)	Failure of HVAC unit.
19. Estimated Damages (structural, contents/vehicle)	\$20K structural, \$20K contents
20. Assisting Agencies like Red Cross, # of displaced?	PNM, New Mexico Gas Co.
21. Contributing factors such as wind or location	None
22. Additional information (rescues, FF injuries and so on)	None
23. On Scene POC	N/A
24. Community Risk Reduction Message	This is an excellent example of the importance of fire/smoke alarms. The alarm system alerted the Fire Department. Fortunately, no occupants were inside residence at the time. Due to the notification by alarm company, damage to the structure and contents was greatly minimized.
25. Additional Information	None